

FROM: START
TO: H -20:00

35L

TIME (NLT)	RESP	ACTION	25X1A	COMPLETED
ASAP	DCOC	Complete & distribute mission alert notification.		Comp K2
ASAP	25X1A DCOC	<input type="checkbox"/> Acknowledge Receipt of <input type="checkbox"/>		Comp K2
ASAP	DCOC	Convert H -hour time to local and record in check list.		Comp K2
ASAP	DCOC	Complete pilots activity schedule (4) (1 - DCO, 1 - M/C, 1 - Flt Surgeon, 1 - CO) DCO		Comp K2
ASAP	25X1A DCO	<input type="checkbox"/>		Comp E. H2
ASAP	DCO	<input type="checkbox"/>		29/2315 E
ASAP	TTFC	Delivers tanker schedule with all C/S - & timing.		20/0250 E
H -23:30(1205L)	DCOC/MC	M/C attend Commander's initial briefing. Receive Ops personnel inputs for recovery team. Give to DCS.		20/1205L
H -23:00(1235L)	SEC	Hangars secured, access lists posted.		20/1225L
H -22:30(1305L)	DCM	Start mission acft preflight (Item 7)		20/0900 K2
H -22:00(1435L)	DCM	Start TEB, LOX, & Refuel. (Item 11)		20/1205 K2
H -22:00(1435L)	COMMO	Recd <input type="checkbox"/> Prepare flimsey		20/1200 E H2
H -21:30(1405L)	Flt Surg	Results of Pilot Physicals	25X1A	20/1200 E H2
H -21:00(1435L)	DCOC	Send <input type="checkbox"/>	25X1A	20/1220 E H2
H -20:30(1505L)	COMMO	Notify DCM of Freq Channelization and translator code.		20/1505 E H2

3450 1450

TO: H -12:00(2335 L)

TIME (NLT)	RESP	ACTION	TIME
H -19:00(1635 L)	DCM	Complete TEB, LOX, & Refuel (Item 11)	#1 20/1930 840
			#2 10A
H -19:00(1635 L)	SEC	Advise M/C of Seat Kit number <u>PARIA KIT #123</u> (ENTER AT BOTTOM OF R-103)	Sec <u>KIT # 105</u>
H -19:00(1635 L)	DCOM	Tape Recorders ready in Briefing Room	1650 L
H -19:00(1635 L)	COMMO	Complete Commo Flimsey, copies to: M/C -3 (2 Pilots + 1 CP) and DCOMF 2	1630 L
H -18:00(1735 L)	DCM	Start INS Preflight (Item 16)	#1 20/1015 Key
			#2 20/1015 Key
H -18:00(1735 L)	DCOMI	Start Intel Briefing <u>Per cmars 821F</u>	1800 L
H -17:00(1835 L)	DCO	Supervise Pilot's initial briefing	1835 L
H -16:00(1935 L)	DCM	Complete INS pre-flight (Item 16)	#1 20/1250 Key
		25X1D	#2 20/1230 Key
H -16:00(1935 L)	DCM	<input type="text"/> pre-flight (Item 17)	#1 20/1445 Key
			#2 1A
H -15:00(2035 L)	DCOM	Notify M/C of Receiving <input type="text"/> 1004 or backup t. type	20/0815 L
H -15:00(2035 L)	COMMO	Deliver <input type="text"/> to M/C if all info available.	20/1700
		25X1A	#1 20/1515 Key
H -13:00(2235 L)	DCM	<input type="text"/> pre-flight (Item 17)	#2 1A
H -13:00(2235 L)	DCM	Start package load (item 20)	(1) 1520 L
			(2) 1A
H -13:00(2235 L)	DCOM	INS load sheet. Deliver to INS	See Page 3
H -13:00(2235 L)	DCM	Notify M/C of receipt of <input type="text"/> (Pkg Data) (1004)	20/0815
		25X1A	20/1233 L
H -12:00(2335 L)	DCOC	Send <input type="text"/>	20/2235 L
H -12:00(2335 L)	F/Surg	Start Crew Rest	

TO: H -2:00(0935 L)

TIME (NLT)	RESP	ACTION	TIME
H -11:30(<u>0005</u> L)	DCOC	Exposure DATA Plg to Pkg Personnel (DCM)	20/2315L
H -11:00(<u>0035</u> L)	DCM	Start <input type="text"/> Beacon 25X1A Check (Item 21)	#1 <u>2300</u> #2 <u>NA</u>
H -9:00(<u>0235</u> L)	DCOW	Five M/C item (G) ^{Wx} effect of ability to launch.	20/2245L
H -9:00(<u>0235</u> L)	DCOC	Send <input type="text"/> to Hqrs 25X1A	20/2203L
H -8:30(<u>0305</u> L)	DCM	Complete Package Load (Item 20)	#1 <u>1723</u> #2 <u>---</u>
H -8:30(<u>0305</u> L)	DCM	25X1A Complete <input type="text"/> Beacon (Item 21)	#1 <u>2330</u> #2 <u>---</u>
H -8:30(<u>0305</u> L)	DCOM	Complete map strip for photo	20/2330L
H -4:30(<u>0705</u> L)	DCOM	Complete film strip	21/0600L
H -4:00(<u>0735</u> L)	AFCS	Report equipment status to DCOC	21/0715L
H -3:45(<u>0750</u> L)	CMDR DCO F/Surg	Final decision on primary & spare pilot, notify DCOL	21/0700L
H -3:45(<u>0750</u> L)	DCO	Current Airfield Status*	21/0750
H -3:30(<u>0805</u> L)	DCM	Start INS warm (Item 30)	21/0800L
H -3:30(<u>0805</u> L)	DCO	Final Briefing* 25X1A	21/0805
H -2:30(<u>0905</u> L)	DCOC	Send <input type="text"/> confirmation of Coord.	21/0950
H -2:00(<u>0935</u> L)	DCOC	Notify Helicopter Section of ETD	21/0935
H -2:00(<u>0935</u> L)	DCOMI	E&E Packet turned in to DCOL	21/0900
H -5:30(<u>0605</u> L)	DCOM	Provide LOAD SHEET TO INS	21/0400
H -5:00(<u>0935</u> L)	DCOM	Provide FINAL Wx FLT PLAN AND OPTIONS	21/0400

TO: L -Hour (1135) L)

TIME (NLT)	RESP	ACTION	TIME
H -1:35(<u>1000</u>) L)	DCOW	Letdown plates to pilots	<u>21/0955L</u>
H -1:30(<u>1005</u>) L)	DCOM	Load both aircraft	#1 <u>21/0945L</u>
H -1:00(<u>option route</u>)			#2
H -1:25(<u>1010</u>) L)	F/Surg	Pre-suitting Physical	<u>21/1015</u>
H -1:00(<u>1035</u>) L)	DCOL	Pilot to aircraft	<u>21/1105</u>
H -1:00(<u>1035</u>) L)	DCO	Go-No-Go decision	<u>21/1100</u>
H -1:00(<u>1035</u>) L)	DCOC	Activate HF	<u>21/09050L</u>
H -1:00(<u>1035</u>) L)	DCOC	Check latest NOTAMS	<u>21/1103L</u>
H -1:00(<u>1035</u>) L)	DCOC	Assure Chopper Alerted	
H -:45(<u>1050</u>) L)	DCOL	Pilot hooked up in acft	<u>21/1210</u>
H -:30(<u>1105</u>) L)	DCM	Start engine	
H -:15(<u>1120</u>) L)	DCOC	Cmdr's emerg C.L., Dash-1, CYG Ck list, B.W. Status Code, in Place	<u>21/1243L</u>
H Hour(<u>1135</u>) L)	DCOC	Send <input type="text"/> 25X1A	<u>21/1243L</u>
H Hour(<u>1135</u>) L)	DCOC	Send T/O Msg to 313th	NR
H +:15(<u>1150</u>) L)	DCOL	Pilot hooked up in spare acft	NR
H +:30(<u>1205</u>) L)	DCM	Start Engine	NR
H +:1:00(<u>1225</u>) L)	DCOC	If spare launches, send <input type="text"/>	NR
		Send T/O Msgt to 313th	NR
H +1:15(<u>1250</u>) L)	DCO	Release Spare (Primary)	NR
30 Min prior to ldg DCOC		Alert Chopper* (Primary)	<u>21/1600L</u>
30 Min prior to ldg DCOC		Notify Transit Alert (Primary)	<u>21/1600L</u>
30 Min prior to ldg M/C		Prepare <input type="text"/> for DTFC or DCO (Clip Bd) (Primary) 25X1A	<u>21/1600L</u>
ASAP	DCOC	If primary aborts, send <input type="text"/> Send Abort Msg to 313th 25X1A	<u>N/A</u>

FROM: L -HOUR (Prim) () L)

TO:

TIME (NLT)	RESP	ACTION	TIME
		(IF SPARE LAUNCHED)	
30 min prior to ldg DCOC		Alert Chopper*	<u>NR</u>
30 min prior to ldg DCOC		Notify Transit Alert	<u>NR</u>
		(IF SPARE ABORTS)	
ASAP	DCOC	Send <input type="text"/> 25X1A	<u>NR</u>
		Send abort msg to 313th 25X1A	<u>NR</u>
ASAP after ldg	DCOC	Send <input type="text"/> (Msn Ldg Report)	<u>21/0738Z</u>
ASAP after ldg	DCOC	Send 313th CNX (ATA) Msg	<u>21/0738Z</u>
ASAP after ldg	DCOC	Receive CYG Down time, then release Strip Alert/Airborne Alert-Tnkr. Notify TTFC.	<u>21/1638Z</u>
ASAP after Ldg	DCOC	Release Helicopter ✓	<u>21/1638Z</u>
ASAP after Ldg	DCOC	Release C-130 (21TCS) ✓	<u>21/1645Z</u>
L +:30	AFCS	Shutdown	<u>21/1645Z</u>
L +1:30	DCOMI	Par "C" of <input type="text"/> to DCOM 25X1A	<u>21/1840</u>
L +3:30	SEC	Sterilize aircraft	<u>21/1807</u>
ASAP after ster- ilization	DCOC	Release aircraft	<u>21/1830</u>
L +5:00	DCO	Review Tanker Msn Report	?
L +5:00	DCOM	Tape of debrief to security	?
L +5:00	COMMO	<input type="text"/> to Security	?

25X1D

307/0
condition

25X1A

FIELD*

	TITLE	DUE		IN	OUT	ACTION	
		LOC	Z				
✓							
✓	Msn Alert Wx Fcst	- 25		X		WX	
		1035				DCO	
✓	Afld Status	Daily			X	DCO	
		09				As of 09	
✓	Tnkr Msn Alert	- 24		X		SAC	
		0135					
✓	Mission Alert	- 24		X		Cmdr, DCO DCM	
		1135					
✓	Ackn Receipt R-54	ASAP			X	DCOC	
		✓					
✓	Mission Plan WX Requirement	- 23		X		WX DCO	
		1235					
✓	Opnl Commo Data	- 22		X		COMMO DCO	
		1335					
✓	25X1D	- 22		X		EWS	
		1335					
✓	Tanker/Wx Scout Recall Word	- 22		X		DCO SAC	
		1335					
✓	Mission Alert Confirmation	- 21			X	DCO	
		1335					
✓	Tanker Support Confirmation	- 21			X	SAC	
		1335					
✓	Msn Pln Wx Fcst	- 21		X		WX	
		1435					
✓	Forward Base Wx Fcsts	- 21		X		WX	
		1435					
✓	Inten- tion Alert	- 20			X	DCO	
	WX Scout Report	1435					

25X1A

FILED IN FOLDER

25X1A

25X1A

XAPPY

	TITLE	DUE		IN	OUT	ACTION	FIELD*
		ICL	Z				
✓	Camera Pkg Data	H - 1300		X		DCOM DCM	25X1A Exposer er Data
✓	Acknowledge Receipt	ASAP			X	DCOC	
✓	Camera Program- ming Data	H - 12:30		X		DCOMP DCM	Probably 1004
✓	Support Request	- 12			X	DCOM DCOC	Prepared By DCOC AND DCOM RETURN TO DCOM FOR CHECKING AND RETURN PRIOR TO TRANSMISSION
✓		- 10			X	COMMO	25X1A
✓	Non Opnl Sortie	Daily NLT 2400L			X	DCO	FILED IN <input type="checkbox"/> FOLDER ext day's al sorties
✓	Special Fuel Test	- 10			X	DCM	25X1D
✓	Forward Base Wx Fcst	- 9			X	WX	
✓	Tanker Pre-Sortie Report	- 9			X	SAC	
✓	GO-NO-GO Wx Forecast	- 9		X		WX DCO	
✓	Pre-Sortie Rpt	- 9			X	DCOC	
✓	Haz Wx Advisory	- 7			X	WX DC	If Advers itions
✓	Haz Wx Advisory	- 7		X		CMOR WX DCO	If Advers itions
✓	Tanker Msn' Sup- port Execution	- 6		X		SAC + DCO	

25X1A

FIELD*

	TITLE	DUE		IN	OUT	ACTION	
		ICL	Z				
✓							
✓	Landing Spare	ASAP			X	DCOC/DCO	
✓	Support Canx Msg	ASAP			X	DCOC/DCO	Give ATA
✓		L + ASAP			X	COMMO	
✓	Msn Post Lndg	L + 2			X	DCO DCOM	
✓	Camera Configuration	L + 3			X	DCM	
✓	Mission Report Directed by	L + 3			X	DCO com	INFO: C "Eyes"
✓	Opnl Sortie Rpt	ASAP			X	DCO m	Same as norma
✓	INS Tape	ASAP			X	DCOM	Via 1004 back-u
✓	Take Progress	ASAP after Take Departure			X	SECURITY	
✓	Final Field Eval of INS Data	L + 24			X	DCM	
✓	Flash Process	ASAP after Processing		X		CMOR DCOM PLM DCO	
✓	Film Evaluation	Developed + 12		X		CMOR DCOM DCM DCO	
✓	INS Tape Eval	NPIC Receipt + 2		X		CMOR DCOM DCO DCM	
✓	INS Film Correle.	L + 7 Days		X		CMOR DCO DCOM DCM	

25X1D

25X1A

message